


PBI1643CE

Electric distribution box, 16A 3p IN/OUT, output sockets 5x16A 3p Shuko



PBI1643PC

Electric distribution box, powerCON IN/OUT, output sockets 5x16A 3p Shuko



PBP1663PC

Electric distribution box, powerCON input, output powerCON x5



PBP1663CE

Electric distribution box, 16A 3p in, output powerCON x5



PBP1683PCT

Electric distribution box, powerCON TRUE input, output powerCON TRUE x5



PBP1683CE

Electric distribution box, 16A 3p in, output powerCON TRUE x5



PBB1687

Electric distribution box, 16A 3p input plug, output sockets 8x16A 3p Shuko



PBB1610

Electric distribution box, 16A 19p input plug, output sockets 6x16A 3p



PBB1632

Electric distribution box, 16A 10p input plug, output sockets 4x16A 3p



PBB1621

Electric distribution box, 16A 16p input plug, output sockets 6x16A 3p




PBB1643

Electric distribution box, 16A 3p input plug, output sockets 6x16A 3p Shuko



PBB3210

Electric distribution box, 32A 3p input plug, output sockets 4x16A 3p



PBQ1654

Electric distribution box, 16A 3p input plug, output sockets 3x16A 3p



PBQ1665

Electr. distrib. box, 16A 3p input plug, output sockets 1x16A 3p, 2xpowerCON OUT



PBQ1676

Electric distribution box, 16A 5p input plug, output sockets 3x16A 3p



PBQ3265

Electric distribution box, 32A 5p input plug, output sockets 3x32A 5p